



Envelope Sealing Performed For:

 Augusta, WI 54722		AEROBARRIER CASE ID: 8246 HARDWARE: AeroBarrier Connect TECHNICIAN: Roland
DATE: 10/22/2021	BUILDING TYPE: Apartment	


Envelope Sealing Results:

<h3><u>BEFORE</u> SERVICE</h3> <p>1468.3 CFM of Leakage, equivalent to a 176.8 Square Inch Hole, or 9.37 Air Changes per Hour</p> <p><small>(for your 1175 square-foot structure enclosing a volume of 9400 cubic feet)</small></p>
<h3><u>AFTER</u> SERVICE</h3> <p>271.9 CFM of Leakage, equivalent to a 32.7 Square Inch Hole, or 1.74 Air Changes per Hour</p>
<p>This corresponds to a 81.5% Reduction in Envelope Leakage</p>
<p>NOTE: Envelope leakage and air-change results are calculated at a standard pressure of 50 Pa.</p>

Envelope Sealing Progress:



Envelope Sealing Performed By:

	Aerostar 221 E Grant st Augusta, WI 54722 Phone: 715-286-5726
---	---

NOTES: a) A certified HVAC contractor or rater should be used to assess the need for enhanced/balanced mechanical equipment as the desired leakage is reduced. b) This certificate provides results based on an enclosure test, using positive pressure. A final blower door test may still be required.

STATE OF STRUCTURE AT TIME OF SEALING:

- **Construction phase:** Finished
- **Number of stories:** 1 on slab
- **Insulation type:** Spray Foam
- **Attic construction:** Unvented
- **Window count:** 8
- **Door count:** 1
- **Bathroom vent count:** 2
- **Range hood count:** 1
- **Fireplace count:** 0
- **Supply & return register count:** 9

Additional structure notes:

AeroSealed Ductwork prior to AeroBarrier


Envelope Sealing Performed For:

<p>[Redacted]</p> <p>Eau Claire, WI 54703</p>		<p>AEROBARRIER CASE ID: 8246</p> <p>HARDWARE: AeroBarrier Connect</p>
<p>DATE: 10/21/2021</p>	<p>BUILDING TYPE: Townhouse</p>	

Envelope Sealing Results:

<p><u>BEFORE</u> SERVICE</p> <p>672.0 CFM of Leakage, equivalent to a 80.9 Square Inch Hole, or 3.21 Air Changes per Hour</p> <p>(for your 1470 square-foot structure enclosing a volume of 12554 cubic feet)</p>
<p><u>AFTER</u> SERVICE</p> <p>194.6 CFM of Leakage, equivalent to a 23.4 Square Inch Hole, or 0.93 Air Changes per Hour</p>
<p>This corresponds to a 71.0% Reduction in Envelope Leakage</p>
<p>NOTE: Envelope leakage and air-change results are calculated at a standard pressure of 50 Pa.</p>

Envelope Sealing Progress:



Envelope Sealing Performed By:

<p>[Redacted]</p>	<p>Aerostar 221 E Grant st Augusta, WI 54722 Phone: 715-286-5726</p>
-------------------	---

NOTES: a) A certified HVAC contractor or rater should be used to assess the need for enhanced/balanced mechanical equipment as the desired leakage is reduced. b) This certificate provides results based on an enclosure test, using positive pressure. A final blower door test may still be required.

STATE OF STRUCTURE AT TIME OF SEALING:

- **Construction phase:** Post Drywall
- **Number of stories:** 1 on slab
- **Insulation type:** Batt
- **Attic construction:** Vented
- **Window count:** 5
- **Door count:** 3
- **Bathroom vent count:** 2
- **Range hood count:** 1
- **Fireplace count:** 0
- **Supply & return register count:** 12